## 限用物質含有情況標示聲明書

Declaration of the Presence Condition of the Restricted Substances Marking

證書號碼/受理編號:(No.) Certificate No/Application No.

商品標籤及商品檢驗標識:(Picture) Product Label and Commodity Inspection Mark.

樣張及其標示位置:(Description and Picture): Picture

Sample and its location.

設備名稱: 印表機,		型號(型式): <u>6180-S10</u>				
Equipment name: POS Printer		Type designation (Type)				
	限用物質及其化學符號					
	Restricted substances and its chemical symbols					
單元 Unit	鉛Lead (Pb)	汞 Mercury (Hg)	鎬 Cadmium (Cd)	六價鉻 Hexavalent Chromium (Cr <sup>+6</sup> )	多溴聯苯 Polybrominated Biphenyls(PBB)	多溴二苯醚 Polybrominated diphenyl ethers (PBDE)
電線	0	0	0	0	0	0
印刷電路板	_	0	0	0	0	0
塑膠	0	0	0	0	0	0
液晶螢幕	0	0	0	0	0	0
軸·金屬軸	0	0	0	0	0	0
金屬零件	0	0	0	0	0	0
齒輪	0	0	0	0	0	0
馬達	0	0	0	0	0	0
计印码	_		$\cap$	$\cap$	$\cap$	

備考 1. "超出 0.1 wt %" 及"超出 0.01 wt %" 係指限用物質之百分比含量超出百分比含量基準值。

Note 1: "Exceeding 0.1 wt %" and "exceeding 0.01 wt %" indicate that the percentage content of the restricted substance exceeds the reference percentage value of presence condition.

備考 2. "○" 係指該項限用物質之百分比含量未超出百分比含量基準值。

Note 2: "o" indicates that the percentage content of the restricted substance does not exceed the percentage of reference value of presence.

備考3. "一"係指該項限用物質為排除項目。

Note 3: The "-" indicates that the restricted substance corresponds to the exemption.